



INTRODUCTION

The purpose of this project is to analyze Maintenance Level 3, 4, and 5 roadways within the Chequamegon-Nicolet National Forest (CNNF) and to provide scientific and quantitative information for the decision maker.

This appendix provides a summary of issue identification response comments for the Forest Level Roads Analysis Process for the CNNF in the Washburn Ranger District. It also provides suggestions for opportunities to minimize impacts and improve the road system.

FOREST ROAD 217

SUMMARY OF COMMENTS AND OPPORTUNITIES

One commenter indicated that Forest Road 217 (Cutacross Road) is in need of erosion control and drainage improvements. The commenter suggested adding gravel to improve the roadway surface.

COMMENTERS

Town of Drummond, Dale Siebert, Foreman

FOREST ROAD 224

SUMMARY OF COMMENTS AND OPPORTUNITIES

One commenter suggested that Forest Road 224 (Star Lake Road) be designated a “Wilderness Road” due to its picturesque views in the North Woods. The commenter also recommended lower travel speeds to enjoy the scenery.

Another commenter indicated that traffic on Forest Road 224 has increased over the past ten years. The commenter suggested adding gravel and improving drainage.

COMMENTERS

Town of Drummond, Dale Siebert, Foreman
Jean Markowski

FOREST ROAD 397

SUMMARY OF COMMENTS AND OPPORTUNITIES

One commenter indicated that traffic on Forest Road 397 has increased over the past ten years. The commenter suggested adding gravel and improving drainage.



COMMENTERS

Town of Drummond, Dale Siebert, Foreman

FOREST ROAD 433

SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters indicated that Forest Road 433 has some steep slopes, which are causing erosion problems. Commenters suggested relocating a portion of the roadway at the Lenawed Creek crossing.

COMMENTERS

USDA Forest Service - CNNF

FOREST ROAD 697

SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters indicated that a portion of Forest Road 697 has erosion problems at two stream crossing locations. Commenters suggested reconstructing a portion of Forest Road 697 at the Fourmile Creek headwaters to reduce impacts.

COMMENTERS

USDA Forest Service - CNNF

FOREST ROAD 847

SUMMARY OF COMMENTS AND OPPORTUNITIES

Commenters indicated that Forest Road 847 is steep and has erosion problems by Bladder Lake. Commenters suggested relocating a portion of the roadway at the south end of Bladder Lake.

COMMENTERS

USDA Forest Service - CNNF
